

Message

---

**From:** Fulper, CarlR [Fulper.Carlr@epa.gov]  
**Sent:** 3/3/2016 7:17:51 PM  
**To:** Snyder, Jim [Snyder.Jim@epa.gov]  
**CC:** Cullen, Angela [cullen.angela@epa.gov]; Nam, Ed [nam.ed@epa.gov]; Wehrly, Linc [wehrly.linc@epa.gov]  
**Subject:** FW: Pictures Requested  
**Attachments:** 20160229\_115032.jpg; 20160229\_120504.jpg; 20160229\_115047.jpg; 20160229\_115241.jpg

Jim,

I found out that you are the VW rep.

Can you tell me if this Jetta has been reflashed? Picture 20160229\_115032.jpg indicated two modifications. Are they related to the exhaust emissions?

Do you have certifications for this 2013 Jetta 2.0L TDI?

I am trying to find a non reflashed vehicle for PEMS testing here to calibration remote sensing data that we have provided to CD (Linc and staff).

Thanks

Carl Fulper  
734-214-4400  
Fulper.carlr@epa.gov

---

**From:** Knott, Dave  
**Sent:** Tuesday, March 01, 2016 10:01 AM  
**To:** Fulper, CarlR <Fulper.Carlr@epa.gov>  
**Subject:** Pictures Requested

For your review and use.

**Dave Knott**  
**Program Manager**  
**Jacobs Technology**  
EPA Contractor  
[knott.dave@epa.gov](mailto:knott.dave@epa.gov)  
EPA Desk 734-214-4381  
Cell 313-971-5553